
# **ASIAS Portal Quick Reference Guide**



# **ASIAS Homepage**

Access to high level findings, studies, and reports





Welcome

Data & Information

### Useful Links

FAA Homepage

Contact Us

### What's New at ASIAS

#### NTSB Weather Related Accidents Study

The number of weather-related accidents from 1994 to 2003 categorized into the following weather events: icing, thunderstorm, turbulence; visibility/ceiling, winds; windshear; precipitation; and other.

"What's New"
section contains the
latest information
and recent studies

#### About ASIAS

### WELCOME TO THE AVIATION SAFETY INFORMATION ANALYSIS AND SHARING (ASIAS) SYSTEM

A facility for the integration, analysis and sharing of aviation safety data and information

The Federal Aviation Administration (FAA) promotes the open exchange of safety information in order to continuously the FAA developed the Aviation Safety Information Analysis and Sharing (ASIAS) system. The ASIAS system enable databases, search an extensive warehouse of safety data, and display pertinent elements in an array of useful formation.

A phased approach continues to be followed in the construction of this system. Additional data sources and capabili both to expanded access to shared data and to technological innovation. Access to the databases and tools alphabetically or by subject

faa.gov | Privacy Policy | Contact Us

Copyright © 2006, Aviation Safety Information Analysis and Sharing, All Rights Reserved.

Date Updated: 19-APR-2007

# **Studies and Reports**





Welcome

Data & Information

Subjects

ects Stud

### Studies



This study examines the issues related to increasing the accessibility of aviation safety data. The issues addressed include identification of safety data resources, format of safety data, analysis and interpretation of safety data, experiences of other Federal agencies with safety data, and public access to safety data.



ASIAS study identifying helicopter accidents occurring between 1990 and 2000 in the NTSB database. Accidents are identified by category of operation, engine type, and type of operation. The study also identifies the top 15 NTSB causal factors by year for helicopter accidents.

### MTSB Weather Related Accidents

The number of weather-related accidents from 1994 to 2003 categorized into the following weather events: icing; thunderstorm; turbulence; visibility/ceiling; winds; windshear; precipitation; and other.

#### Review of Aviation Accidents Occurring in the State of Alaska, 1992-2001

A detailed review of Part 91, 135, and 121 aviation accidents occurring in the state of Alaska between the years 1992 and 2001. The study examines operational factors such as phase of flight, type of aircraft, and meteorological conditions, as well as a breakout of the NTSB causal and contributing factors.

### Turbulence Study

Weather Turbulence Study focusing on accidents that occurred from 1992 to 2001 in the United States. The study breaks out the Federal Aviation Regulation Operating Rules (Part 91, 121, etc.) for a detailed review including injuries, location, and type of turbulence.


faa.gov | Privacy Policy | Contact Us

Copyright @ 2006, Aviation Safety Information Analysis and Sharing. All Rights Reserved.


Date Updated: 19-APR-2007



# **Studies and Reports**



Examples of ASIAS Studies



Par	rt 91:	Part	135:	Part	135:	Part	121:	All O	ther	
General Aviation		Air Taxi		Commuter		Air Carrier		Operations		Total
VMC	IMC	VMC	IMC	VMC	IMC	VMC	IMC	VMC	IMC	Accidents*
767	20	7	0	0	0	0	0	6	0	810
144	4	159	21	31	9	2	0	18	1	392
200	23	50	7	19	10	2	0	13	0	330
5	3	3	2	2	4	14	1	4	2	42
3	0	0	0	1	0	1	0	2	0	10
0	2	0	0	0	0	0	0	0	0	2
1,119	52	219	30	53	23	19	1	43	3	1,586
	General VMC 767 144 200 5 3	VMC         IMC           767         20           144         4           200         23           5         3           3         0           0         2	General Aviation         Air 1           VMC         IMC         VMC           767         20         7           144         4         159           200         23         50           5         3         3           3         0         0           0         2         0	General Aviation         Air Taxi           VMC         IMC         VMC         IMC           767         20         7         0           144         4         159         21           200         23         50         7           5         3         3         2           3         0         0         0           0         2         0         0	VMC         IMC         VMC         IMC         VMC         VMC <td>General Aviation         Air Taxi         Commuter           VMC         IMC         VMC         IMC         VMC         IMC           767         20         7         0         0         0           144         4         159         21         31         9           200         23         50         7         19         10           5         3         3         2         2         4           3         0         0         0         1         0           0         2         0         0         0         0</td> <td>General Aviation         Air Taxi         Commuter         Air C           VMC         IMC         VMC         IMC         VMC         IMC         VMC           767         20         7         0         0         0         0         0           144         4         159         21         31         9         2           200         23         50         7         19         10         2           5         3         3         2         2         4         14           3         0         0         0         1         0         1           0         2         0         0         0         0         0</td> <td>General Aviation         Air Taxi         Commuter         Air Carrier           VMC         IMC         IMC         VMC         IMC         VMC         IMC         IMC         VMC         IMC         IMC         VMC         VMC         IMC         VMC         VMC</td> <td>VMC         IMC         VMC         IMC         IMC         VMC         IMC<td>General Aviation         Air Taxi         Commuter         Air Carrier         Operations           VMC         IMC         VMC         VMC         IMC         VMC         IMC         VMC         <t< td=""></t<></td></td>	General Aviation         Air Taxi         Commuter           VMC         IMC         VMC         IMC         VMC         IMC           767         20         7         0         0         0           144         4         159         21         31         9           200         23         50         7         19         10           5         3         3         2         2         4           3         0         0         0         1         0           0         2         0         0         0         0	General Aviation         Air Taxi         Commuter         Air C           VMC         IMC         VMC         IMC         VMC         IMC         VMC           767         20         7         0         0         0         0         0           144         4         159         21         31         9         2           200         23         50         7         19         10         2           5         3         3         2         2         4         14           3         0         0         0         1         0         1           0         2         0         0         0         0         0	General Aviation         Air Taxi         Commuter         Air Carrier           VMC         IMC         IMC         VMC         IMC         VMC         IMC         IMC         VMC         IMC         IMC         VMC         VMC         IMC         VMC         VMC	VMC         IMC         IMC         VMC         IMC <td>General Aviation         Air Taxi         Commuter         Air Carrier         Operations           VMC         IMC         VMC         VMC         IMC         VMC         IMC         VMC         <t< td=""></t<></td>	General Aviation         Air Taxi         Commuter         Air Carrier         Operations           VMC         IMC         VMC         VMC         IMC         VMC         IMC         VMC         VMC         VMC         VMC         VMC         VMC         VMC         VMC         VMC         VMC <t< td=""></t<>

\*Total Accidents include accident counts for those events where the meteorological condition was unknown.


Review of Aviation Accidents Occurring in the State of Alaska, 1992 - 2001



# **Databases Arranged by Subjects**



### **Data and Information**





The Accident/Incident Data System (AIDS) database contains data records for general aviation and commercial air carrier incidents since 1978. The ASIAS database for AIDS contains incidents only because ASIAS uses the National Transportation Safety Board (NTSB) accident database as the primary source for accident information. The information contained in AIDS is gathered from several sources including incident reports on FAA Form 8020-5.

### Air Registry (AR)

The FAA aircraft registry is a data system used to record and track civil aircraft registered in the United States. Registration occurs at the Federal Aviation Administration in Oklahoma City where the appropriate information is obtained and recorded from the aircraft purchaser. The database is updated in real time as the registry staff obtain and enter the data into the data system. The Registry maintains the permanent records of over 320,000 active civil aircraft and provides approximately 700 copies of aircraft records daily for review to users of the Public Documents Room located in the Registry Building at the Mike Monroney Aeronautical Center in Oklahoma City, Oklahoma.

### Aviation Safety Reporting System (ASRS)

The Aviation Safety Reporting System (ASRS) receives, processes, and analyzes reports of unsafe occurrences and hazardous situations that are voluntarily submitted by pilots, air traffic controllers, and others. Information collected by the ASRS is used to identify hazards and safety discrepancies in the National Airspace System. It is also used to formulate policy and to strengthen the foundation of aviation human factors safety research.

### Bureau of Transportation Statistics (BTS)

The Bureau of Transportation Statistics (BTS) database contains traffic and capacity statistics on individual Air Carrier operations. BTS is an administration under the Department of Transportation (DOT), at a similar organizational level as the FAA. During the 1970s, when the Civil Aeronautics Board (CAB) was disestablished, the CAB Bureau of Accounts and Statistics came to be what is now the BTS office of Airline Statistics.




# **Using the Database Query Tools**




### **Database Information**








### **Database Search**



# **Query Results**



### **Event Details**

Occurrence #: 1 IN FLIGHT ENCOUNTER WITH WEATHER Phase of Operation: CRUISE - NORMAL

#### Findings

	Event Seq#	Event Group Code	Subject	Modifier	Personnel	Cause/Factor
l	1	1	WEATHER CONDITION	TURBULENCE		CAUSE

### AIRCRAFT 1 PRELIMINARY REPORT

Search terms highlighted in the narrative fields.

On April 29, 2005, approximately 0731 central daylight time, a twin-turbofan Boeing 737-700 airplane, N727SW, operating as Southwest Airlines flight number 2440, was undamaged during an in-flight encounter with turbulence while in cruise flight at Flight Level 410 (41,000 feet mean seal level) near Little Rock, Arkansas. The airline transport rated captain, airline transport rated first officer, two of the three flight attendants, and 15 passengers were not injured. One flight attendant was seriously injured. The arrolage was registered to and operated by Southwest Airlines, of Dallas, Texas. Visual meteorological conditions prevailed, and an instrument flight rules flight plan was filed for the scheduled passenger flight operating under 14 Code of Federal Regulations Part 121. The cross-country flight originated from the William P. Hobby Airport (HOU), near Houston, Texas, at 0637 and was destined for the Lambert-St. Louis International Airport (STL), near St. Louis, Missouri, where the flight landed without further incident. The 12.500-hour captain reported in the Pilot/Operator Aircraft Accident Report (NTSB/Form 6120.1/2) that while in cruise flight at FL410 (41,000 feet msl), there was no turbulence and the flight was above an overcast cloud layer for most of the flight. The captain stated that visibility was limited at times due to a thin layer of haze. As a precaution, the captain kept the fasten seat belt sign on and instructed the flight attendants to take their seats if the flight became "wimpy." Several minutes later, the flight encountered a thin layer of haze. Upon exiting the layer of haze, the flight crew noticed "an unusual cloud formation" directly ahead. The captain initiated a right turn as the flight encountered "two abrupt bumps and a gain in air speed." The captain added that the encounter lasted about 15-20 seconds, which was light to moderate turbulence. Following the turbulence upset, the captain was notified by a cabin crew member that a flight attendant sustained a leg injury in the aft galley, and would need medical attention upon arrival at STL. A staff meteorologist for the Safety Board reviewed composite reflectivity images for the immediate area of the turbulence encounter. The satellite imagery at 1215Z indicated radiative Aud top temperature of 218.3 degrees Kelvin (K) or -54.86 degrees Celsius (C). The winds aloft at FL410 were reported from 280 degrees at 127 knots. Convective significant meteorological information (SIGMETs) were issued from 0955Z through 1255Z for thunderstorm activity. Convective SIGMET 18C issued at 1155Z was current for a portion of Arkansas and Oklahoma, enclosed from 10ENE TUL-40WSW ARG-20ENE LIT-20NE MLC-10ENE TUL. For an intensifying area of severe embedded thunderstorms moving from 260 degrees at 35 knots, with tops to 40,000 feet. Hail to 1 1/2 inches and wind gusts to 60 knots were possible with these storms. Severe to extreme turbulence, lightning, microburst, severe icing, and localized IFR conditions was implied with the issuance of the advisory. The provided coordinates of the turbulence upset was located outside and immediately east of the convective SIGMET in affect.

### AIRCRAFT 1 FINAL REPORT

During cruise flight at FL410, the scheduled domestic passenger flight encountered moderate turbulence. The passengers were seated and the fasten seatbelt sign was illuminated. The flight attendants were instructed to take their seats "if it gets bumpy." During the turbulence encounter, a flight attendant was injured by a beverage cart. The flight continued to its intended destination and landed uneventfully.